

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

DATAMASTER MAINTENANCE REPORT

RECEIVED DHSS Breath Acotol Program
By Carol Day at 7:37 am, Sep 03, 2009

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file. 970025 Louisiana LOCATION OF INSTRUMENT (STREET AND CITY South CHECKLIST: Place a check (✓) to the left of each item if found to be satisfactory of if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument. M DIAGNOSTIC CHECK (PRINTOUT ATTACHED) COMPUTER DETECTOR PROGRAM FILTERS HEATERS SAMPLE CHAMBER 49 °C QUARTZ STANDARD FLOW DETECTOR CALIBRATION PRINTER Y PUMP HIGH SPEED INDICATOR LIGHTS TIME AND DATE SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34.0 CALIBRATION CHECK -Run three tests using a standard solution. All three tests must be within \pm 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used, (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP) ☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE O.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) . 098 TEST 1 PERFORM R.F.I. TEST (PRINTOUT ATTACHED) M NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS (DO NOT INCLUDE SIMULATOR TESTS) REFUSALS *** (.05-.09)(.10-.14) (.15-.19) (Over .19) • List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary) adjust voltages. Install new EPROM and EXP 04/08/10 RACEY DURBIN Lot #09/20 INSPECTING OFFICER



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 09120 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1198 percent (w/vol) ethyl alcohol. The expiration date for this lot number is April 8, 2010 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- 2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURI LOUISIANA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 970025

TESTING OFFICER: DURBIN/T

OFFICER I.D.: 4567

PERMIT NUMBER: 920026

EXPIRATION DATE: 02/18/11

MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLANK TEST INTERNAL STANDARD EXTERNAL STANDARD BLANK TEST EXTERNAL STANDARD BLANK TEST EXTERNAL STANDARD	.000 VERIFIED .098 .000 .098 .000	13:0 13:0 13:0 13:0 13:0
EXTERNAL STANDARD BLANK TEST	. 099 . 000	13:05 13:05 13:06

N = 3 SIM. = .1 AVG. = .0983 Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI LOUISIANA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 970025 08/27/09 12:59

--- DIAGNOSTIC CHECK ---

COMPUTER:

OKAY

PROGRAM (04-07-2009):

OKAY

HEATERS

SAMPLE CHAMBER:

49c

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED:

OKAY

DETECTOR:

OKAY

FILTERS:

ÜKAY

QUARTZ STANDARD:

OKAY

CALIBRATION:

OKAY

PRINTER TEST

!"#\$%%'()*+,-./0123456789:;<=>?@ABCDEFG HIJKLMYOPORSTUVWXYZ[\]^_'abcdefahijklmno parstuvwxaz{|}>+

Operator Signature_____

Operator Signature_

2208-0

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI LOUISIANA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 970025 08/27/09

ARREST TIME: 09:00
SUBJECT NAME:
LKKLLL
DOB: 07/07/07 SEX: M
STATE/D.L.: MO/TTTTT
ARRESTING OFFICER:
RRRR
OFFICER I.D.: RRRR
TESTING OFFICER:
DURBIN/T
OFFICER I.D.: 4567
PERMIT NUMBER: 920026
EXPIRATION DATE: 02/18/11
MISCELLANEOUS DATA:

--- BREATH AMALYSIS ---

BLAMK TIEST	.000	13:13
INTERNAL STANDARD	VERIFIED	13:13
SUBJECT SAMPLE	.096	13:14
BLANK TEST	.000	13:15
ALTHUR CLAST	. 555	10:13

7 Seconds

Operator Signature____

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MISSOURI LOUISIANA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 970025 08/27/09

ARREST TIME: 09:00 SUBJECT NAME: LKKLLL DOB: 07/07/07 SEX: M STATE/D.L.: MO/TTTTT ARRESTING OFFICER: RRRRR OFFICER I.D.: RRRR TESTING OFFICER: DURBIN/T OFFICER I.D.: 4567 PERMIT NUMBER: 920026 EXPIRATION DATE: 02/18/11 MISCELLANEOUS DATA: RFI/CHECK

--- BREATH ANALYSIS ---

BLANK TEST .000 13:11 INTERNAL STANDARD VERIFIED 13:11 RADIO INTERFERENCE

Operator Signature_

2208-02

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



TRACEY DURBIN

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER;INTOXILYZER 5000;ALCO-SENSOR IV/RBT IV

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577:041, RSMo 1986.

Date <u>02/18/09</u>	John of Mathewson	
Number 920026	Director of State Public Health Laboratory	
02/18/2011 Expires	Margart T. Donnelly	
	- Director, Department of Health	
MO 580-0771 (7-88)	Lab. 4 (R7-88)	